

Engineering Bulletin – CD i Revision 1

CD i integrated CD player

- Change R606 from 100R to BLM18SG121TN1D
- Change R621 from 100R to 47R (0603)
- Change R622 from 100R to 47R (0603)
- Change RP603 from 100R to 47R (CAY16-470J4LF)
- Change IC606 from SN74HC161PWT to SN74LV161APW (4bit synchronous binary counter)