

Engineering Bulletin – CD i Revision 3

CD i integrated CD player

- Remove Schurter fuse and fuse clips from FS801
- Solder Bussman fuse (SR-5-1A-AP) across pads as shown below:

