



Cyrus Audio Ltd  
Ermine Business Park  
Huntingdon  
Cambridgeshire, PE29 6XY  
+44(0)1480 435 577  
[service@cyrusaudio.com](mailto:service@cyrusaudio.com)

## Engineering Bulletin – Servo PCB

---

LYRIC, THREE, CD Xt Sig, CD t, CD i

### Summary

This change is required to improve the disc loading recognition for semi-transparent discs.

The following component should be replaced as follows:

- Change R408 47R (SMD0603 1%) to 470R (SMD0603 1%).